



To,

21.06.2021

Deputy I  
Electrical Inspector,  
Office of the Electrical Inspector,  
Bengaluru South, No. 95, 1<sup>st</sup> Floor,  
Gandhi Bazar Main Road, Basavanagudi,  
Bengaluru – 560004.

Subject: Completion Report as per your observation about out Electrical  
at ISME, on 12.02.2021

Dear Sir,

This is with reference to the Electrical Inspectorate audit findings after inspection, given to ISME; we would like to mention that we have taken care of the points raised in the report.

We would like to mention here that due to Covid and the volatile working conditions; we have done all the necessary points, which was put as rectifying points. Specially the danger boards, painting of the mesh and clearing of the transformer area.

The electrical room is cleaned as per the requirement. Hence, please find this completion report for your records and acknowledgement.

For International School of Management Excellence

  
Authorised Signatory



Enclosed your report for immediate reference